Problem: Jackpot Reset Key Doesn't Function Properly

WIRE CONTINUITY TEST
Common lead to J/P10-7
Normally open lead to J/P10-15

MOTHERBOARD CONTINUITY CHECK
J/P10-15 to J/P1-22B
J/P10-7 to J/P10-16

PROCESSOR BOARD TEST
Test U5 - if problem continues, then replace
Test U14 - if problem continues, then replace
Test U21 - if problem continues, then replace
Test U12 - if problem continues, then replace
Test RP6 - if problem continues, then replace

Problem: Can't Access Self Test Mode

WIRE CONTINUITY TEST
J/P3-14 to J/P3-13

MOTHERBOARD CONTINUITY CHECK
J/P3-13 to J/P1-19B

PROCESSOR BOARD TEST
Test U6 - if problem continues, then replace
Test U5 - if problem continues, then replace
Test U14 - if problem continues, then replace
Test U21 - if problem continues, then replace
Test U12 - if problem continues, then replace
Test RP5 - if problem continues, then replace