




Bally Power Supply



Problems That I have Found.



Bally Power Supply Various BV errors –



C5 - 100uF 400v cap (this one has a dome top)

C101 – 100 uF 25v
C103 - 4.7 uF 50v
IC 102 – UC3844N

C7 – 2200 uF 16v
C10 – 2200 uF 10v
C9 – 2200 uF 10v
C12 – 470 uF 25v
C11 – 2200 uF 10v
C8 – 1000 uF 16v

My Slot Notes (RESULT) Robert E. Sult AOS